



Note : IO39,IO40 don't have a terminating resistor because it is the power status for the DDS chassis.

ARECIBO OBSERVATORY		
BY : BILL SISK		
FILE : DDS1.SCH		
Title		
DDS CONTROLLER		
Size	Document Number	Rev
B	IPACK BOARD	0
Date:	Wednesday, December 10, 2003	Sheet 1 of 1