



R.T. Time (10 nsec / small div)

- from HF3B-100.s1p (pre-1st-arc-damage, 10 April 2015)
- from 20Aug3B.s1p (check of FINALLY-repaired 1st-arc damage, 20 Aug)
- pre-repair_2nd-arc (antenna instead of short at end) (8.543m O.W.) t14Sep18.s1p
- post-repair_2nd-arc with short at far end (22 Sept 2015) arc2fixd.s1p
- post-repair_2nd-arc with antenna instead of short (22 Sept 2015) ant2fixd.s1p

HF3B-100.s1p (pre-1st-arc file)
 HF3B-x1x.s1p (repaired post-1st-arc file)
 23jun3b.s1p (retry later to see any changes)
 01Jul3b.s1p (a week later)
 20Aug3B.s1p (following wholesale repl of last 50 ft or so of line)
 farlin4c.exe
 plot bin limits 8300:9520
 goodnarr.fc7
 newbadnarr.fc7
 23Jun3B.fc7
 t14sep18.s1p
 t14sep18.fc7
 01Jul3B.fc7
 20Aug3B.fc7

Dana Whitlow
 22 Sept 2015
 new_mix_narr_2nd_arc_post-repair.fc7