




15jun13gregorian position




16jun13gregorian position




17jun13gregorian position








18jun13_1gregorian position




18jun13_2gregorian position







15jun13 gr motor torques at failure




16jun13 gr motor torques at failure




17jun13 gr motor torques at failure




18jun13_1 gr motor torques at failure




18jun13_2 gr motor torques at failure




15jun13 gr motor torques at failure




16jun13 gr motor torques at failure



17jun13 gr motor torques at failure



18jun13_1 gr motor torques at failure



18jun13_2 gr motor torques at failure

