




Overplot jan,mar spectra with preamp off. (PoIY)



Overplot jan,mar spectra with preamp on (PoIY)



Compare Tflange postamp off, before after cable change



Compare Tflange postamp on, before after cable change

