




05sep15: 2380 MHz rfi. sbn 750 IF, skyCFR:2380MHz,A/D cfr:2380MHz




sbn 750 IF, skyCfr:2370MHz,A/D cfr:2370MHz




sbn 10GhzUpConverter IF, skyCfr:2380MHz, A/D cfr:2380MHz



sbn 10GhzUpConverter IF, skyCfr:2385MHz. A/D cfr:2380MHz



sbn 10GhzUpConverter IF, skyCfr:2385MHz. A/D cfr:2385MHz



sbw 10GhzUpConverter IF, skyCfr:2360MHz. A/D cfr:2360MHz

