




# Status Bit Change with commands vertex general status (page 2)




vertex axis status (page 3)



### dome axis mode (page 4)



### dome equipment status



dome amp status (page 5)

