



Time (10 nsec / small div)

- from HF3B-100.s1p (pre-arc-damage, 10 April 2015)
- from HF3B-x1x.s1p (repaired post-arc-damage, 18 June 2015)
- from 23Jun3B.s1p (recheck of repaired post-arc-damage, 23 June)
- from 01Jul3B.s1p (recheck of repaired post-arc-damage, 01 July)
- from 20Aug3B.s1p (check of FINALLY-repaired damage, 20 Aug)

Dana Whitlow
21 Aug 2015
new_mix_narr.fc7

HF3B-100.s1p (pre-arc file)
 HF3B-x1x.s1p (repaired post-arc file)
 23jun3b.s1p (retry later to see any changes)
 01Jul3b.s1p (a week later)
 20Aug3B.s1p (following wholesale repl of last 50 ft or so of line)
 farlin4c.exe
 plot bin limits 8300:9520
 goodnarr.fc7
 newbadnarr.fc7
 23Jun3B.fc7
 01Jul3B.fc7
 20Aug3B.fc7